

## CUSUM, MA and EWMA Control Charts

Increasing the sensitivity and getting ready for automated control:


The Cumulative Sum chart, the Moving Average and the Exponentially Weighted Moving Average Charts.

### Shewhart Charts cannot detect small shifts

The charts discussed so far are variations of the *Shewhart* chart: each new point depends only on one subgroup.


Shewhart charts are sensitive to large process shifts.

The probability of detecting small shifts fast is rather small:



## Cumulative-Sum Chart

If each point on the chart is the *cumulative history* (integral) of the process, systematic shifts are easily detected. Large, abrupt shifts are not detected as fast as in a Shewhart chart.



CUSUM charts are built on the principle of *Maximum Likelihood Estimation* (MLE).

## Maximum Likelihood Estimation

The "correct" choice of probability density function (pdf) moments maximizes the collective likelihood of the observations.

If  $x$  is distributed with a pdf( $x, \theta$ ) with unknown  $\theta$ , then  $\theta$  can be estimated by solving the problem:


$$\max_{\theta} \left[ \sum_{i=1}^m \text{pdf}(x_i, \theta) \right]$$

This concept is good for estimation as well as for comparison.

## Maximum Likelihood Estimation Example

To estimate the mean value of a normal distribution, collect the observations  $x_1, x_2, \dots, x_m$  and solve the maximization problem:


$$\max_{\mu_{\text{est}}} \left\{ \prod_{i=1}^m \frac{1}{\sigma\sqrt{2\pi}} e^{-\frac{1}{2} \left( \frac{x_i - \mu_{\text{est}}}{\sigma} \right)^2} \right\}$$



## MLE Control Schemes

If a process can have a "good" or a "bad" state (with the control variable distributed with a pdf  $f_G$  or  $f_B$  respectively).

This statistic will be small when the process is "good" and large when "bad":



## MLE Control Schemes (cont.)

Note that this counts from the beginning of the process. We choose the best  $k$  points as "calibration" and we get:

$$S_m = \sum_{i=1}^m \log \frac{f_B(x_i)}{f_G(x_i)} - \min_{k < m} \sum_{i=1}^k \log \frac{f_B(x_i)}{f_G(x_i)} > L$$

or

$$S_m = \max \left( S_{m-1} + \log \frac{f_B(x_m)}{f_G(x_m)}, 0 \right) > L$$

This way, the statistic  $S_m$  keeps a cumulative score of all the "bad" points. Notice that we need to know what the "bad" process is!

## The Cumulative Sum chart

If  $\theta$  is a mean value of a normal distribution, is simplified to:

$$S_m = \sum_{i=1}^m (\bar{x}_i - \mu_0)$$

where  $\mu_0$  is the target mean of the process. This can be monitored with V-shaped limits.


### Advantages

The Cusum chart is very effective for small shifts and when the subgroup size  $n=1$ .

### Disadvantages



The Cusum is relatively slow to respond to large shifts. Also, special patterns are hard to see and analyze.

### Example



### The CUSUM design


Need to set  $L(0)$  (i.e. the run length when the process is in control), and  $L(\delta)$  (i.e. the run-length for a *specific* deviation).



## The CUSUM design

$$d = \left( \frac{2}{\delta^2} \right) \ln \left( \frac{1-\beta}{\alpha} \right)$$

$$\theta = \tan^{-1} \left( \frac{\delta}{2A} \right) \quad \delta = \frac{\Delta}{\sigma_{\bar{x}}}$$



## ARL vs. Deviation for CUSUM



$\delta$  = Deviation from Target Value (in standard deviations)

$L(\delta)$  = Average run length when process is in control.

|      |                                    | 50    | 100   | 200   | 300   | 400   |
|------|------------------------------------|-------|-------|-------|-------|-------|
| 0.25 | $(4/\sigma_{\bar{x}}) \tan \theta$ | 0.125 |       |       | 0.195 |       |
|      | $d$                                | 47.6  |       |       | 46.2  |       |
|      | $L(0.25)$                          | 26.1  |       |       | 71.0  |       |
| 0.50 | $(4/\sigma_{\bar{x}}) \tan \theta$ | 0.25  | 0.28  | 0.29  | 0.28  | 0.28  |
|      | $d$                                | 17.5  | 18.2  | 21.4  | 24.7  | 27.3  |
|      | $L(0.5)$                           | 15.8  | 19.0  | 24.0  | 26.7  | 29.0  |
| 0.75 | $(4/\sigma_{\bar{x}}) \tan \theta$ | 0.375 | 0.475 | 0.375 | 0.375 | 0.275 |
|      | $d$                                | 9.2   | 11.1  | 13.8  | 15.0  | 16.7  |
|      | $L(0.75)$                          | 8.9   | 11.0  | 13.4  | 14.5  | 15.7  |
| 1.0  | $(4/\sigma_{\bar{x}}) \tan \theta$ | 0.50  | 0.50  | 0.50  | 0.50  | 0.50  |
|      | $d$                                | 5.7   | 6.9   | 6.2   | 6.0   | 6.6   |
|      | $L(1.0)$                           | 6.1   | 7.4   | 8.7   | 9.4   | 10.0  |
| 1.5  | $(4/\sigma_{\bar{x}}) \tan \theta$ | 0.75  | 0.75  | 0.75  | 0.75  | 0.75  |
|      | $d$                                | 2.7   | 3.1   | 3.9   | 4.3   | 4.5   |
|      | $L(1.5)$                           | 3.4   | 4.0   | 4.6   | 5.0   | 5.2   |
| 2.0  | $(4/\sigma_{\bar{x}}) \tan \theta$ | 1.0   | 1.0   | 1.0   | 1.0   | 1.0   |
|      | $d$                                | 1.5   | 1.9   | 2.2   | 2.1   | 2.3   |
|      | $L(2.0)$                           | 2.0   | 2.65  | 2.96  | 3.15  | 3.3   |

## CUSUM chart of furnace Temperature difference

Detect  $2C^\circ$ ,  $\sigma = 1.5C^\circ$ ,  $\alpha = .0027$   $\beta = 0.05$ ,  $\theta = 18.43^\circ$ ,  $d = 6.6$



Lecture 14: CUSUM and EWMA

13

## Tabular CUSUM

A tabular form is easier to implement in a CAM system


$$S_H(i) = \max [ 0, \bar{x}_i - (\mu_0 + K) + S_H(i-1) ]$$

$$S_L(i) = \max [ 0, (\mu_0 - K) - \bar{x}_i + S_L(i-1) ]$$

$$S_L(0) = S_H(0) = 0$$

$$K = \Delta/2$$

$$H = d\sigma_x \tan(\theta)$$




Lecture 14: CUSUM and EWMA

14

## Cusum Enhancements

To speed up CUSUM response one can use "modified" V masks:



Other solutions include the application of Fast Initial Response (FIR) CUSUM, or the use of combined CUSUM-Shewhart charts.

## General MLE Control Schemes

Since the MLE principle is so general, control schemes can be built to detect:

- single or multivariate deviation in means
- deviation in variances
- deviation in covariances

An important point to remember is that MLE schemes need, implicitly or explicitly, a definition of the "bad" process.

The calculation of the ARL is complex but possible.



## Control Charts Based on Weighted Averages

Small shifts can be detected more easily when multiple samples are combined.

Consider the average over a "moving window" that contains  $w$  subgroups of size  $n$ :

$$M_t = \frac{\bar{X}_t + \bar{X}_{t-1} + \dots + \bar{X}_{t-w+1}}{w}$$

$$V(M_t) = \frac{\sigma^2}{n w}$$

The 3-sigma control limits for  $M_t$  are:


$$UCL = \bar{\bar{X}} + \frac{3\sigma}{\sqrt{n w}}$$

$$LCL = \bar{\bar{X}} - \frac{3\sigma}{\sqrt{n w}}$$

Limits are wider during start-up and stabilize after the first  $w$  groups have been collected.

## Example - Moving average chart

$$w = 10$$



## The Exponentially Weighted Moving Average

If the CUSUM chart is the sum of the entire process history, maybe a weighed sum of the recent history would be more meaningful:

$$z_t = \lambda \bar{x}_t + (1 - \lambda) z_{t-1} \quad 0 < \lambda < 1 \quad z_0 = \bar{\bar{x}}$$


It can be shown that the weights decrease geometrically and that they sum up to unity.


$$z_t = \lambda \sum_{j=0}^{t-1} (1 - \lambda)^j \bar{x}_{t-j} + (1 - \lambda)^t z_0$$

$$UCL = \bar{x} + 3 \sigma \sqrt{\frac{\lambda}{(2 - \lambda) n}}$$

$$LCL = \bar{x} - 3 \sigma \sqrt{\frac{\lambda}{(2 - \lambda) n}}$$

## Two example Weighting Envelopes





## Another View of the EWMA

- The EWMA value  $z_t$  is a *forecast* of the sample at the  $t+1$  period.
- Because of this, EWMA belongs to a general category of filters that are known as “time series” filters.

$$\hat{x}_t = f(x_{t-1}, x_{t-2}, x_{t-3}, \dots)$$

$$\hat{x}_t - x_t = a_t$$

Usually:

$$\hat{x}_t = \sum_{i=1}^p \phi_i x_{t-i} + \sum_{j=1}^q \theta_j a_{t-j}$$

- The proper formulation of these filters can be used for forecasting and feedback / feed-forward control!
- Also, for quality control purposes, these filters can be used to translate a non-IIND signal to an IIND residual...

## Summary so far..

While simple control charts are great tools for visualizing the process, it is possible to look at them from another perspective:

Control charts are useful “summaries” of the process statistics.

Charts can be designed to increase sensitivity without sacrificing type I error.

It is this type of advanced charts that can form the foundation of the automation control of the (near) future.

Next stop before we get there: multivariate and model-based SPC!