
EE 245 Discussion Section 9/12/2011


 Unless otherwise noted, all material taken from Senturia Microsystems Design: http://www.springerlink.com/content/978-0-7923-7246-2/


Accelerometers: F = ma




Capacitive Sensing








Piezoelectric Sensing







Shear Mode

Shear mode designs bond, or "sandwich," the sensing crystals between a center post and seismic mass. A compression ring or stud applies a preload force required to create a rigid linear structure. Under acceleration, the mass causes a shear stress to be applied to the sensing crystals.


This system has an undamped resonant frequency ω_o equal to $\sqrt{k/m}$ and a quality factor Q equal to $m\omega_o/b$.




We examine, first, the signal term, then the noise term. The inertial force F equals the proof mass m times the acceleration to be measured, denoted here by a. This, together with the definition of ω_o , leads to a fundamental characteristic of quasi-static accelerometers. The displacement and acceleration are scaled by the square of the resonance frequency:



We now consider the intrinsic noise due to damping. The spectral density function of the force noise is $4k_BTb$, just like Johnson noise in a resistor. This noise typically arises from fluid damping. It is called *Brownian motion noise*, although in fact, the form of the force-noise spectral density function does not depend on the specific mechanism producing the damping.



In practice, the signal-to-noise ratio, and, hence, the achievable accelerometer sensitivity, is dominated by other effects: the noise contributed by the position-measuring circuit, especially its first stage of amplification: the need to build additional stiffness into the structure (raising its resonant frequency) to prevent either sticking of parts during fabrication or excess fragility; or residual calibration errors and drift problems. We now consider position measurement methods.





 Other important factors to consider are voltage supply (sensitivity and range) and application (power)