Decimal Numbers: Base 10

Digits: 0, 1, 2, 3, 4, 5, 6, 7, 8, 9

Example:

3271 =

$$(3\times10^3) + (2\times10^2) + (7\times10^1) + (1\times10^0)$$

Numbers: positional notation

- Number Base B ⇒ B symbols per digit:
  - Base 10 (Decimal): 0, 1, 2, 3, 4, 5, 6, 7, 8, 9
    Base 2 (Binary): 0, 1
- Number representation:
  - $d_{31}d_{30}$ ... d_1d_0 is a 32 digit number
  - value = $d_{31} \times B^{31} + d_{30} \times B^{30} + ... + d_1 \times B^1 + d_0 \times B^0$
- Binary: 0,1 (In binary digits called "bits")
  - 0b11010 = $1\times2^4 + 1\times2^3 + 0\times2^2 + 1\times2^1 + 0\times2^0$
    = 16 + 8 + 2
    = 26

#s often written 0b…

- Here 5 digit binary # turns into a 2 digit decimal #
- Can we find a base that converts to binary easily?

Hexadecimal Numbers: Base 16

- Hexadecimal:
  0, 1, 2, 3, 4, 5, 6, 7, 8, 9, A, B, C, D, E, F
  - Normal digits + 6 more from the alphabet
  - In C, written as 0x… (e.g., 0xFAB5)
- Conversion: Binary⇔Hex
  - 1 hex digit represents 16 decimal values
  - 4 binary digits represent 16 decimal values
  - ⇒1 hex digit replaces 4 binary digits
- One hex digit is a "nibble". Two is a "byte"
- Example:
  - 1010 1100 0011 (binary) = 0x_____ ?

Decimal vs. Hexadecimal vs. Binary

Examples:

1010 1100 0011 (binary)
= 0xAC3

10111 (binary)
= 0001 0111 (binary)
= 0x17

0x3F9
= 11 1111 1001 (binary)

How do we convert between hex and Decimal?

00	0	0000
01	1	0001
02	2	0010
03	3	0011
04	4	0100
05	5	0101
06	6	0110
07	7	0111
08	8	1000
09	9	1001
10	A	1010
11	B	1011
12	C	1100
13	D	1101
14	E	1110
15	F	1111

MEMORIZE!

Kilo, Mega, Giga, Tera, Peta, Exa, Zetta, Yotta

physics.nist.gov/cuu/Units/binary.html

- Common use prefixes (all SI, except K [= k in SI])

Name	Abbr	Factor	SI size
Kilo	K	2^{10} = 1,024	10^3 = 1,000
Mega	M	2^{20} = 1,048,576	10^6 = 1,000,000
Giga	G	2^{30} = 1,073,741,824	10^9 = 1,000,000,000
Tera	T	2^{40} = 1,099,511,627,776	10^{12} = 1,000,000,000,000
Peta	P	2^{50} = 1,125,899,906,842,624	10^{15} = 1,000,000,000,000,000
Exa	E	2^{60} = 1,152,921,504,606,846,976	10^{18} = 1,000,000,000,000,000,000
Zetta	Z	2^{70} = 1,180,591,620,717,411,303,424	10^{21} = 1,000,000,000,000,000,000,000
Yotta	Y	2^{80} = 1,208,925,819,614,629,174,706,176	10^{24} = 1,000,000,000,000,000,000,000,000

- Confusing! Common usage of "kilobyte" means 1024 bytes, but the "correct" SI value is 1000 bytes
- Hard Disk manufacturers & Telecommunications are the only computing groups that use SI factors, so what is advertised as a 30 GB drive will actually only hold about 28 x 2^{30} bytes, and a 1 Mbit/s connection transfers 10^6 bps.

kibi, mebi, gibi, tebi, pebi, exbi, zebi, yobi

en.wikipedia.org/wiki/Binary_prefix

- New IEC Standard Prefixes [only to exbi officially]

Name	Abbr	Factor
kibi	Ki	2^{10} = 1,024
mebi	Mi	2^{20} = 1,048,576
gibi	Gi	2^{30} = 1,073,741,824
tebi	Ti	2^{40} = 1,099,511,627,776
pebi	Pi	2^{50} = 1,125,899,906,842,624
exbi	Ei	2^{60} = 1,152,921,504,606,846,976
zebi	Zi	2^{70} = 1,180,591,620,717,411,303,424
yobi	Yi	2^{80} = 1,208,925,819,614,629,174,706,176

As of this writing, this proposal has yet to gain widespread use…

- International Electrotechnical Commission (IEC) in 1999 introduced these to specify binary quantities.
  - Names come from shortened versions of the original SI prefixes (same pronunciation) and *bi* is short for "binary", but pronounced "bee" :-(
  - Now SI prefixes only have their base-10 meaning and never have a base-2 meaning.

The way to remember #s

- What is 2^{34}? How many bits addresses (I.e., what's `ceil` $\log_2$ = `lg` of) 2.5 TiB?
- Answer! 2^{XY} means…

X=0 ⇒ ---	Y=0 ⇒ 1
X=1 ⇒ kibi ~10^3	Y=1 ⇒ 2
X=2 ⇒ mebi ~10^6	Y=2 ⇒ 4
X=3 ⇒ gibi ~10^9	Y=3 ⇒ 8
X=4 ⇒ tebi ~10^{12}	Y=4 ⇒ 16
X=5 ⇒ pebi ~10^{15}	Y=5 ⇒ 32
X=6 ⇒ exbi ~10^{18}	Y=6 ⇒ 64
X=7 ⇒ zebi ~10^{21}	Y=7 ⇒ 128
X=8 ⇒ yobi ~10^{24}	Y=8 ⇒ 256
	Y=9 ⇒ 512



MEMORIZE!